

Photo Album for Enfield Fire District, CT Job 35175 February 05, 2021

In this report your cab is in assembly while the frame was built, the pump house is staged, and the body has begun initial assembly. In your next report the cab may be merged with the chassis followed by the pump house and the body is staged.



DSC02482




DSC02483



DSC02484




DSC02485




DSC02486



DSC02487



DSC02488



DSC02489



DSC02490




DSC02491



DSC02178




DSC02179




DSC02180



DSC02181



DSC02182



DSC02183



DSC02184



DSC02185



DSC02186



DSC06533



DSC06534



DSC06535



DSC06536



DSC06537



DSC02117




DSC02118



DSC02119



DSC02120



DSC02121




DSC02122




DSC02123



DSC02124




DSC02125



DSC02126



DSC02127



DSC02128



DSC02129



Firematic

SUPPLY COMPANY, INC

www.Firematic.com



An Oshkosh Corporation Company



Your Vision to Quality & Safety



©2005- 2021 Fire & Safety Consulting, LLC
Neenah, Wisconsin 54956