Photo Album for Enfield Fire District, CT Job 36277 March 04, 2022

In this report your cab started assembly, pump house completed paint and continued assembly, the body modules completed fabrication and began the paint process, and the torque box remained staged with no photos. In your next report your cab may continue assembly, the pump house may continue assembly, and the body modules may continue through paint. The torque box will remain staged with no photos until assembly begins.





DSC04757





DSC04759 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



DSC04758





DSC00124





DSC00126 © 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



DSC00125







DSC04614



DSC05190



DSC04615

© 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







DSC05192



DSC05191



© 2005 - 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956



www.Firematic.com



An Oshkosh Corporation Company



©2005- 2022 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956

