

TRUCK COMMITTEE ENGINE 12 REPLACEMENT

February 2022

GOALS

- To replace a 1996 Fire Engine located at Station # 2 with new similar apparatus as recommended by a committee.
- To reduce the Fire Department Fleet by selling one Fire Engine at Station # 1 and not replacing it.
- To put a substantial down-payment using funds previously set aside for replacement apparatus.
- To benefit from low interest rates to fund the remainder of the cost.
- To have a replacement Fire Engine that meets the current safety standards and requirements.

ONE APPARATUS WILL REPLACE TWO



Engine #12 1996 Pierce Lance Quint – Squirt (26 years old)
Will be replaced with a modern similar unit



Engine #5 2005 Seagrave Marauder Quint – Meanstick (17 years old)

Apparatus reduction / Will be sold and not replaced

EXPECTATIONSNew Engine

- Ladder aluminum or steel 75 foot
- Cross lays 3 preferred / 2 minimum
- Rear lays LDH 1000 800 feet preferred / 500 minimum
- handline 1 rear hook-up 1 ¾ or 2 ½ 300 foot preferred
- ∘ **Pump size** 1250 minimum
- **Ground ladder storage** 6 preferred / 5 minimum
- Seating 6 preferred / 5 minimum
- **Tank size** 500 gal minimum
- **Engine** 400 HP minimum
- Scene lighting yes
- Color solid red to match existing
- Additional equipment none needed



WHERE CAN I GET MORE INFORMATION?

Please call or email -Deputy Chief Bill Higgins:

Phone: (860) 741-3114 Monday - Friday days

Email: EFDWHiggins@enfield.org anytime